54

FORM MR-AR (Revised 12/90)



DIVISION OF OIL, GAS & MINING

STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS AND MINING

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

Telephone: (801) 538-5340

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

. GEN	ERAL INFORMATION
1.	Report Time Period: From (mo./yr.) <u>Jan 90</u> To (mo./yr.) <u>Jan 91</u>
2.	DOGM File Number (original notice): M /037/006
3.	Mine Name: Rim-Columbus Mine
4.	Legal Description (Location of Lands Affected):
	1/4,1/4, Section <u>29</u> , Township <u>31S</u> , Range <u>25E</u>
	1/4,1/4, Section, Township, Range
	1/4,1/4, Section, Township, Range
5.	Mineral(s) Mined: <u>Uranium and Vanadium</u>
6.	Name of Operator or Company: <u>Umetco Minerals Corporation</u>
7.	Permanent Address: Mr. Niels B. Haubold
	P 0 Box 1029
	Grand Junction, CO 81502

	8.	Company Representative (or designated operator):
		Name: Mr. James L. Hasty
		Title: <u>Mine_Foreman</u>
		Address: PO Box 506, Dove Creek, CO 81324
		Phone: 303-677-2711
		Please check if any of the above information has changed since previous year.
II.		MINING AND RECLAMATION
	1.	Was the mine active during the past year? Yes $f f X$ No $ \Box$
	2.	If active, how much ore or mineral was mined? 12,100 Tons
	3.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected. No new areas were disturbed. About 9,600 tons of rock were
		added to existing waste stockpiles.
	4.	Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results.
		No areas were reclaimed during the year.
	5.	What was the total unreclaimed acreage at years end? 13

6. Briefly summarize mining and reclamation planned for the upcoming year. Production ceased at the mine on December 1, 1990, and the plan is to keep it on standby until the market for uranium and vanadium justifies a reopening. Most likely, the mine will be on standby for one year.

NOTE: Section III., "Additional Information" applies only to <u>large</u> mining operations.

III. ADDITIONAL INFORMATION

- 1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
- 2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Mr. Niels B. Haubold

Title of Operator:

Manager of Mines

Signature of Operator:

Mels B. Haubold

Date: 1-28-91

jb MNMR-AR